

TVM Rifle Cleaning Steps

Supplies needed: Fouling scraper, patches, Type F Transmission Fluid, Minwax finishing wax, a quality gun oil, and toothpick.

1. Apply minwax to stock. Do not wipe off at this time.
2. Run fouling scraper down barrel and turn to the right a couple of times. Empty fouling from barrel.
3. Place toothpick in vent liner. Pour warm soapy water down barrel and let sit about 5 minutes.
4. Empty water from barrel. Remove toothpick and start running patches down barrel. When the patches come out clean and dry, then run a patch with a good gun oil down the barrel.
5. Remove the 2 lock bolts and gently work the lock from the stock. Wipe both sides of the lock and replace.
6. Now buff the wax from the stock.
7. Apply the Type F Transmission Fluid to all outside surfaces (wood and metal), but not inside the barrel or back of lock.